

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG.10




FIG. 11




FIG. 12A




FIG. 12B




FIG. 13A




FIG. 13B




FIG. 14




FIG. 15A




FIG. 15B

Abnormality Level	Contract 1	Contract 2
	High Amount Low Risk	Reasonable Some Risk
High	Replacement (Urgent)	Replacement (Urgent)
Medium	Replacement (In Regular Maintenance)	Replacement (In Regular Maintenance)
Low	Replacement (In Regular Maintenance)	--
Normal	--	--

FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 22




FIG. 23